



Sir Safety System S.p.A. Single-member company Wholly-owned subsidiary of Sir Holding Srl Via dei Fornaciai, 9 - Santa Maria degli Angeli 06081 Assisi - Perugia - Italy Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548 Viale Europa 74 20090 Cusago Milano Tel. +39 02.90394575 Fax +39 02.90394441

export@sirsafety.com www.sirsafety.com





Name: VELVET COLOR BIB-TROUSERS Code: MC3613ED MC36 HIGH VISIBILITY CLOTHING - WINTER

Description

High visibility bib-trousers made of fluorescent yellow Velvet fustian fabric 60% cotton and 40% polyester, weight 350 g/m, with zipper and button closure, two slanted side pockets, tridimensional functional pocket with flap and Velcro with left pen holder, ruler pocket on right leg, rear pocket with flap and button. Jointed double stitching in the most vulnerable areas. Top part in high visibility yellow and bottom part of the legs, belt and pocket flaps in blue.

One loop of reflective band around the waist and two loops around the

- The Velvet range offers high visibility requirements and guarantees cold resistance and insulation.
- Fabric with double inner plush lining.
- The compact fabric retains body heat and its surface enhances the ability to repel liquid and dirt.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments

Regulation (EU) 2016/425 and subsequent amendments.		
EN ISO20471 Class 2: - Á0.50 m fluoresce - Á0.13 m reflective		
Category II	Colours HI-VIS YELLOW/BLUE	Available Sizes Made to order: 44, 48, 60 In stock:
Quantity/Carton 20	EC Standards EN ISO 20471 Class:2	Important Information General and Road Construction, Road sign work, Road and plants maintenance, Service and assistance companies, Emergency response companies. The performances of the garment are guaranteed when it is correctly worn and fastened. Keep in a cool dry place, farfrom heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it. We recommend to follow the washing instructions.
Dexterity		Storage and cleaning